

Tools Needed:



Screw Driver

Included:




(2) Ganging Plates



(16) Screws

2

Assembly - Step 1:



Line up ganging plates with pre-drilled holes on the underside of the front and rear of the training table(s).

Secure with included screws to join the two tables together.

3